Alaska Marine Highway System - Pelican Ferry Renovation	Ferminal	FY2012 Request: Reference No:	: \$3,000,000 51835
AP/AL: Allocation	Project Ty	/pe: Renovation an	d Remodeling
Category: Transportation			
Location: Pelican	House Dis (HD 2)	strict: Sitka/Wrang	ell/Petersburg
Impact House District: Sitka/Wrangell/Petersburg (HD 2)	Contact:	Pat Kemp, Deputy (Commissioner
Estimated Project Dates: 07/01/2011 - 06/30/2018	3 Contact P	hone: (907)465-39	000
Appropriation: Surface Transportation Program			
Brief Summary and Statement of Need:This is a new capital request because of a STIP and release of the Governor's FY2012 budget. The replat dock, including but not limited to superstructure, sub other improvements as needed. This project contribu- injuries, fatalities and property damage and by impro- Funding:FY2012FY2013FY2013FY2014Fed Rcpts\$3,000,000Total:\$3,000,000\$0\$0	acement of fe ostructure, an utes to the Doving the mol FY2015 \$0	rry transfer ramps and fenders; provide epartment's Mission bility of people and FY2016 FY2016 FY2016	and platform area lighting, and n by reducing goods. <u>(2017 Total</u> \$3,000,000 \$0 \$3,000,000
	ed - new	Phased - underway	On-Going
0% = Minimum State Match % Required	dment	Mental Health Bill	
Operating & Maintenance Costs: Project Deve Ongoing C	elopment:	Amount	Staff
	Operating: <u>e Startup:</u> Totals:	0 0 0	0 0

Additional Information / Prior Funding History:

None.

Project Description/Justification:

The Pelican Ferry Terminal is located near the south end of the Pelican Boat Harbor and consists of a fixed platform dock, two tidal ramps and ancillary mooring structures. The facility was originally constructed in 1975 with extensive modification in 1980. The dock and ramps are hollow-core precast concrete panels supported by galvanized steel beams and pipe piles. Treated bull rails are bolted to the longitudinal edges of the dock and ramps.

The lower portion of the low-tide ramp is often submerged in seawater and the concrete decking and steel substructure are severely deteriorated. Several lineal feet of the cores in the precast panels have ruptured and there are numerous penetrations through the panels. The failed condition of the low-tide ramp required a bridge closure in 2005. An emergency repair, consisting of timber mats bridging the damaged concrete panels, currently permits use of the low tide ramp at a reduced load rating.

The general condition of both tide ramps and dock is poor. All concrete panels exhibit heavy efflorescence and the corrosion protection of the piles and steel framing is exhausted. The bull rails provide inadequate protection for vehicles and pedestrians. Timber fenders along the seaward face Department of Transportation and Public Facilities Reference No: 51835 6/28/11 5:36:08 PM Page 1 Released June 29th, 2011

FY2012 Request:

Reference No:

of the dock have failed and provide no protection from vessel collision. Recommended action:

- Remove and dispose of existing concrete superstructure and steel substructure.

- Furnish and install approximately 6,000 sq ft platform dock and twin tidal ramps consisting of: Galvanized steel pipe piling and steel framing,

Precast solid concrete planks or concrete filled steel grid decking, and Bridge and pedestrian steel tube railing.

- Furnish and install 6 modular fenders each with energy absorbing rubber elements, and
- Furnish and install area lighting.