Terminal Boiler Plume Mitigation				Reference No: 58643			
AP/AL: Allocation				Project Type: Construction			
Category: Tr	ansportation						
Location: Anchorage Areawide				House District: Anchorage Areawide (HD 11-27)			
Impact House District: Anchorage Areawide (HD 11-27)				Contact: Steven Hatter			
	roject Dates: (n: Airport Impr			Contact I	Phone: (907)	269-0730	
Brief Summary and Statement of Need: This project is to mitigate the vapor plume from one of six boilers at the South Terminal and is Phase 1 of a project to complete the work on all boilers. After a season or two of evaluating the success of Phase 1 in mitigating the plume, a determination will be made on how to proceed with Phase 2, mitigation of the plume on the remaining boilers.							
Funding:	FY2015	FY2016	FY2017	FY2018	FY2019	FY2020	Total
Fed Rcpts Int Airprt	\$510,000 \$34,000						\$510,000 \$34,000
Total:	\$544,000	\$0	\$0	\$0	\$0	\$0	\$544,000
State Match Required One-Time Project Phased					Phased - un	,	n-Going
0% = Minimum State Match % Required ☐ Amendm				ment	□ Mental Hea	lth Bill	
Operating &	Maintenance (<u>Am</u>	<u>ount</u>	<u>Staff</u>
Project Develo				•		0	0
Ongoing Operat				erating:		0	0

FY2015 Request:

\$544,000

Prior Funding History / Additional Information:

Ted Stevens Anchorage International Airport - South

No prior funding history

Project Description/Justification:

A scoping study to mitigate the identified possible hazard was accomplished in early 2013. The study identified 7 alternative solutions to mitigate the vapor plume formation. Two options were evaluated using a life-cycle cost (LCC) analysis. The solution recommended in the study (and accepted by ANC) was estimated to have a \$2.1 LCC for all six boilers and was ~\$160,000 above the second alternative but had a significantly greater likelihood of effective mitigation.

One-Time Startup:

Totals:

This project responds to an April 25, 2013 FAA Determination of Hazard to Air Navigation. The determination identifies a possible hazard/visual obstruction regarding ATCT line of sight to movement surfaces caused by moisture vapors from the South Terminal's boiler exhaust.

0

0