Central Reg Repairs	gion Hightower	Emergenc	y Maintenance a	and	FY2010 Reque Reference No		\$365,500 48920
AP/AL: Allocation				ct Type	e: Construction		
Category: 7	Fransportation		-				
Location: Anchorage Areawide				Contact: Frank Richards			
House District: Anchorage Areawide (HD 17-32)				Contact Phone: (907)465-3900			
Estimated Project Dates: 04/19/2010 - 12/31/2011							
Appropriation: Emergency Repairs							
, pp. op. and		(opano					
Brief Summary and Statement of Need:							
This request will fund emergency repairs to hightower lighting structures in Central Region.							
Funding:	FY2010	FY2011		-Y2013	FY2014	FY2015	Total
Gen Fund	\$365,500						\$365,500
Total:	\$365,500	\$0	\$0	\$0	\$0	\$0	\$365,500
	+)	T -	T -	• -	• -	• -	¥ ,
State Match Required V One-Time Project Phased - new					Phased - underw	vav 🗌 On-	-Going
	n State Match % Re	•			Mental Health B	•	Conig
0,0				•			
Operating 8 Maintenance Costa							Staff
Operating & Maintenance Costs:				- 1 -	Amour		Staff
		ŀ	Project Developm			0	U
			Ongoing Opera	0		0	0
			One-Time Sta	rtup:		0	

Additional Information / Prior Funding History:

None.

Project Description/Justification:

Inspections of hightower lighting structures in Central Region have identified work that needs to be performed on 17 of these structures in order for them to remain structurally sound. This work includes welding repairs and foundation bolt tightening. The repairs will require the use of specialized equipment, crane services, materials, labor, and contracted welding/engineering support.

Totals:

Damage to the electrical system has occurred to a hightower lighting structure at the Seward Highway/Rabbit Creek Road Interchange in Anchorage. Repairs to this structure will require the structure to be removed from its foundation and placed on the ground. Requested funding will support costs of contracted crane services, materials, and labor required to conduct repairs.

If funding is not provided, the safety of the traveling public is at risk from failure of the structures and insufficient lighting of our roadways.

0

0