




Dalton Highway

August 2011

Jeff Russell

Northern Region Maintenance & Operations, Dalton District Superintendent


Highway Overview



- Dalton Highway 414 Miles
- Built to secondary road standards and completed in 1975
- The State took over maintenance in 1978
- Opened to public in 1994
- Intense truck traffic, 60% to 80% of traffic is heavy trucks
- ▶ 32 bridges
- Hundreds of culverts
- ▶ 7 maintenance camps
- ▶ 6 main airports
- Traffic increased over 25% since 2005 and projected to increase 25% from 2011 to 2014.

Present Highway Situation

- 40% has been reconstructed to a 32 foot hard surface with improved shoulders, drainage and turn out areas
- ▶ \$27,000/mile in maintenance costs
- Poor road geometry, blind curves, steep grades up to 12%



Maintenance Issues

- Permafrost subsidence
- Increasing gravel surfacing wear
- Seeps and springs in cut slopes create icing problems
- Lack of embankments high enough to prevent snow drifting
- Federal funds cannot be used for routine maintenance
- The only way to better accomplish the needed maintenance is to commit additional resources







2011 Federal Capital Projects

MP 55.5 Yukon River Bridge Seismic Retrofit

- Total cost about \$790,000
- MKB Constructors
- ▶ 80% complete
- ▶ MP 260 321 Culverts
 - ▶ Total cost about \$17,000,000
 - Granite Construction Co.
 - ▶ 85% complete
- ▶ Dalton MP 254 414 Delineators
 - ▶ Total cost about \$2,300,000
 - Granite Construction Co.
 - ▶ 50% complete
- ▶ Dalton 274 289 Rehabilitation
 - Total cost about \$27,600,000
 - Alaska Interstate Construction, LLC.
 - ▶ 10% complete





2011/2012 Anticipated GF Projects

- MP 19-23 Repair slopes and embankment failures
- MP 90-175 High float and undulation repair
- MP 209-415 Calcium chloride dust palliative application (various areas)
- MP 315-321 Grade raise
- MP 334-362 High float and undulation repair
- MP 358 Grade raise and surface leveling with high float

Increase safety areas at the Galbraith and Prospect Airports



2012 Anticipated Federal Capital Projects

- Dalton 9 Mile North
 - Tentative advertise November 2011
- MP II-18 Reconstruction
 - Tentative advertise November 2011
- MP 197-209 Rehabilitation
 - Tentative advertise October 2011



Past General Fund Capital Projects

FY2010		 MP 19-23 – Repair slopes and embankment failures MP 90-175 – High float repairs MP 209 -415 – Calcium chloride dust palliative application (various areas) MP 242 – Guardrail replacement
		 MP 246 Atigun Pass guardrail replacement MP 314 - 315 Reshape and surface MP 326 - Ice Cut guardrail replacement MP 358 Grade raise and resurface with high float MP 377-415 - Resurface MP 58.3, 66.7, and 71.1 - Deep culvert replacement
FY2009		 MP 0-28 – Widen, drainage, resurface MP 56-90 – Grade, drainage, resurface MP 228-229 – Grade raise and resurface MP 241-242 – Grade raise and resurface
FY2009	\$14 million (GO Bond)	 MP 144-175 – Brush cutting, undulation, drainage, high float repair MP 242-247 – Guardrail replacement MP 325-334 – Road widening, grade raise, resurface MP 246 – Atigun Pass – guardrail replacement, 4.5 miles MP 334-362 – Grade, undulation, delineators, high float repair

Past General Funds Projects

FY2008	\$9 million	 MP 22-56 – Widen, culvert, brush cutting and resurfacing MP 70 – Multi-plate culvert replacement MP 90-175 – High float repairs MP 175-209 – Brush cutting, guardrail, culverts and resurfacing MP 175-415 – Calcium chloride MP 209-234 – Grade, drainage, brush cutting, resurfacing MP 243-259 – High float application MP 334-362 – High float repairs MP 362-415 – Delineator replacement
FY2007	\$9 million	 MP 90-175 – High float and embankment repairs MP 237-263 – Resurfacing MP 362-378 – Resurfacing MP 362-415 – Dust palliative and delineator replacement
FY2006	\$6 million	 MP 90-175 – Differential settlement repairs MP 254-335 – Dust palliative, brush cutting, and delineator replacement MP 289-306 – Resurfacing MP 306-316 – Dust palliative and resurfacing MP 362-415 – Dust palliative

Future Needed Projects - Unfunded

While the department has made considerable improvements with the funds that have been provided since 2005 there is still a considerable backlog of capital projects to be completed.

Also many of the initial project areas have succumbed to the growing traffic numbers, requiring another surface overlay to keep a suitable and maintainable driving

surface.



Contact Information

Bill O'Halloran

Northern Region Maintenance & Operations Director bill.ohalloran@alaska.gov 907.451.2295





Alaska Department of Transportation & Public Facilities 2301 Peger Road Fairbanks, AK 99709

Jeff Russell
Dalton District Superintendent
jeff.russell@alaska.gov
907.451.2207

