

Ted Stevens Anchorage International Airport - Terminal Seating

FY2012 Request: \$1,700,000
Reference No: 51619

AP/AL: Allocation

Project Type: Construction

Category: Transportation

Location: Anchorage Areawide

House District: Anchorage Areawide (HD 17-32)

Impact House District: Anchorage Areawide (HD 17-32)

Contact: Marc Luiken

Estimated Project Dates: 07/01/2011 - 06/30/2018

Contact Phone: (907)269-0730

Appropriation: Airport Improvement Program

Brief Summary and Statement of Need:

Provide new public seating in the terminal building. Much of the existing seating is in poor condition and some areas do not have an adequate amount of seating. This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.

Funding:	FY2012	FY2013	FY2014	FY2015	FY2016	FY2017	Total
Int Airprt	\$1,700,000						\$1,700,000
Total:	\$1,700,000	\$0	\$0	\$0	\$0	\$0	\$1,700,000

<input type="checkbox"/> State Match Required	<input type="checkbox"/> One-Time Project	<input checked="" type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
0% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

Operating & Maintenance Costs:

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	0
Totals:	0	0

Additional Information / Prior Funding History:

None.

Project Description/Justification:

Furnish and install new public seating in the North Terminal (NT) and the main ticket lobby, main bag claim lobby, and concourses A, B and C of the South Terminal where Anchorage International Airport (ANC) owns and provides the public seating.

Much of the ANC owned public area seating in the terminal buildings is over 20-years old (30 years NT), and is comprised of several different colors and styles, and is worn out. The cushion coverings are split or ripped. Cushion stuffing falling out causes a continuous need to vacuum carpets. Joints in the supporting frames are cracked or broken. Arm rest coverings are split or ripped. Some arm rests are missing. In several locations there is not enough seating of one style or color to keep from having to mix styles or colors. Several units are disposed every year because they cannot be repaired. A large portion of customer complaints are directed towards the poor condition and comfort of the public area seating. In the past several years repair costs have been high.