

**Tok Cutoff - Tok River Bridge Replacement**

**FY2014 Request: \$12,000,000**

**Reference No: 56925**

**AP/AL:** Allocation  
**Category:** Transportation  
**Location:** Tok

**Project Type:** Construction

**House District:** Bering Straits/Interior Villages (HD 39)

**Impact House District:** Bering Straits/Interior Villages (HD 39)

**Contact:** Pat Kemp

**Estimated Project Dates:** 07/01/2013 - 06/30/2020 **Contact Phone:** (907)465-3900

**Appropriation:** Surface Transportation Program

**Brief Summary and Statement of Need:**

Replace Tok River bridge (#0663) at MP 104 of Tok Cutoff Highway.

<b>Funding:</b>	<u>FY2014</u>	<u>FY2015</u>	<u>FY2016</u>	<u>FY2017</u>	<u>FY2018</u>	<u>FY2019</u>	<u>Total</u>
Fed Rcpts	\$12,000,000						\$12,000,000
<b>Total:</b>	\$12,000,000	\$0	\$0	\$0	\$0	\$0	\$12,000,000

<input checked="" type="checkbox"/> State Match Required	<input checked="" type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
9% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

**Operating & Maintenance Costs:**

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	
<b>Totals:</b>	<b>0</b>	<b>0</b>

**Prior Funding History / Additional Information:**

No prior funding history

**Project Description/Justification:**

An inspection of the bridge has determined that there are several deficiencies which include the following: Concrete pier wall between fluted steel piles is extensively cracked transversely near waterline at Pier 4. The Pier 4 wall is anchored to steel girder diaphragms with cables near abutment 5. Other pier walls are transversely cracked near waterline. Minor drift on upstream nose of Pier 2. New pourable joint seals have been installed over piers. Pier 2 joint seal is cracked, but intact. Pier 4 joint is in fair condition with some cracks.