Rehabilitation **Reference No:** 58648 **Project Type:** Construction AP/AL: Allocation **Category:** Transportation **Location:** Yakutat **House District:** Kodiak/Cordova (HD 35) Impact House District: Kodiak/Cordova (HD 35) **Contact:** Steven Hatter Estimated Project Dates: 07/01/2014 - 06/30/2019 Contact Phone: (907)269-0730 **Appropriation:** Airport Improvement Program **Brief Summary and Statement of Need:** This project will include milling and patching the existing surface, and the construction of a new surface that is designed to mitigate the effects of the high groundwater. Additional work will include pavement improvements in adjacent taxiway and apron areas as necessary. Funding: FY2015 FY2016 FY2017 FY2020 FY2018 Total Fed Rcpts \$10,000,000 \$10,000,000 \$10,000,000 \$10,000,000 Total: \$0 \$0 \$0 \$0 ☐ State Match Required ☐ One-Time Project ☐ Phased - new Phased - underway ☐ On-Going 0% = Minimum State Match % Required ☐ Amendment □ Mental Health Bill **Operating & Maintenance Costs:** Amount Staff

FY2015 Request:

\$10,000,000

0

0

0

Prior Funding History / Additional Information:

Yakutat - Airport Runway, Taxiway and Apron

No prior funding history

Project Description/Justification:

Pavement on Yakutat's primary runway has a low pavement condition index (PCI) and requires resurfacing. The combination of Yakutat's flat topography which does not facilitate effective drainage and its high ground water has resulted in ice blisters in the runway – small, raised areas that result from ice forming under the pavement -- and relatively rapid deterioration of the runway pavement.

Project Development:

Ongoing Operating:

One-Time Startup:

Totals:

0

0

0

0