

**Galena - Airport Improvements**

**FY2016 Request: \$13,500,000**

**Reference No: 60523**

**AP/AL:** Allocation  
**Category:** Transportation  
**Location:** Galena

**Project Type:** Construction  
**House District:** Bering Straits/Yukon Delta (HD 39)

**Impact House District:** Bering Straits/Yukon Delta (HD 39)

**Contact:** Jeff Ottesen

**Estimated Project Dates:** 07/01/2015 - 06/30/2020

**Contact Phone:** (907)465-4070

**Appropriation:** Airport Improvement Program

**Brief Summary and Statement of Need:**

Resurface Runway 7/25 and Taxiway "B", repair the General Aviation Apron and complete other improvements as funding allows.

<b>Funding:</b>	FY2016	FY2017	FY2018	FY2019	FY2020	FY2021	Total
Fed Rcpts	\$13,500,000						\$13,500,000
<b>Total:</b>	\$13,500,000	\$0	\$0	\$0	\$0	\$0	\$13,500,000

<input checked="" type="checkbox"/> State Match Required	<input checked="" type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
5% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

**Operating & Maintenance Costs:**

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	0
<b>Totals:</b>	<b>0</b>	<b>0</b>

**Prior Funding History / Additional Information:**

No prior funding history.

**Project Description/Justification:**

This Galena Airport Runway and Taxiway B received a Pavement Condition Index (PCI) score below 54 and are recommended for rehabilitation in the 2012 Pavement Inspection Results.

A PCI below 70 for Runways and below 60 for other airfield surfaces is an indication that a project should be programmed in the short term for reconstruction under the Pavement Management System. Poor pavement conditions result in Foreign Object Debris (FOD) on aprons, runways and taxiways and are safety concerns for aircraft moving on the airfield. Damage to aircraft and surface transportation vehicles can result from these conditions.

The airport's operational surfaces are deteriorated and are beyond their usable life.