

Ted Stevens Anchorage International Airport: Department of Homeland Security Renovation **FY2006 Request: \$2,700,000**
Reference No: AMD 40304

AP/AL: Allocation **Project Type:** Construction

Category: Transportation

Location: Anchorage Areawide

Contact: Kip Knudson

House District: Anchorage Areawide (HD 17-32) **Contact Phone:** (907)269-0724

Estimated Project Dates: 07/01/2005 - 06/30/2010

Appropriation: Airport Improvement Program

Brief Summary and Statement of Need:

Renovate existing space to improve customs inspections and expedite handling of foreign visitors. This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.

Funding:	FY2006	FY2007	FY2008	FY2009	FY2010	FY2011	Total
IntAptCons	\$2,700,000						\$2,700,000
Total:	\$2,700,000	\$0	\$0	\$0	\$0	\$0	\$2,700,000

<input type="checkbox"/> State Match Required	<input checked="" type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
0% = Minimum State Match % Required		<input checked="" type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

Operating & Maintenance Costs:

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	
Totals:	0	0

Additional Information / Prior Funding History:

None.

Project Description/Justification:

This project will complete the Inspection area relocation to the second level in the International Passenger Terminal. Inspection of passengers must be completed before they can access their baggage in order to meet Customs Technical Facility Requirements. The International facility was built prior to these requirements and required passengers to claim bags first and process through immigration last. The Airport had to move passenger inspection booths to the second level and to build a corridor that separates arriving passengers from departing passengers. However, all labs, diagnostic and forensic equipment are located on the first floor. Customs must close the processing line and go to the first level to use the labs and equipment if they determine that a passenger and/or documents need further inspection. This project completes the renovation by moving labs and equipment to the second level to be near the passenger arrival corridor. This improvement will help maintain the department's Port-of-Entry status with Customs.