5		
Location: Anchorage Areawide House District: A	Anchorage Are	
	Anchorage Are	
32)	House District: Anchorage Areawide (HD 17- 32)	
<b>Impact House District:</b> Anchorage Areawide (HD <b>Contact:</b> Marc Lu 17-32)	uiken	
Estimated Project Dates: 07/01/2011 - 06/30/2018 Contact Phone: Appropriation: Airport Improvement Program	(907)269-0730	)
Brief Summary and Statement of Need:The department recently completed a reconciliation of construction bond funds and determined thatthere is sufficient bond authority in a previous authorization available. This amendment to the FY12Governor's budget request reduces the construction bond funds by \$250,000 for a new requestedbond amount of \$50,000. This project will purchase residential dwellings and land within the LakeHood Strip Runway Protection Zone (RPZ) and remove the dwellings.Funding:FY2012FY2013FY2014FY2016FY2017Total		
Fed Rcpts \$950,000   IntAptCons \$50,000	2010 1120	\$950,000 \$50,000
Total: \$1,000,000 \$0 \$0 \$0	\$0	\$0 \$1,000,000
	ed - underway	On-Going
Operating & Maintenance Costs: Project Development: Ongoing Operating: One-Time Startup:	Amount 0 0 0	Staff 0 0

## Additional Information / Prior Funding History:

\$5,000,000 - Ch 15 SLA 2009 Sec 1 pg 28 ln 16 for land acquisition.

## **Project Description/Justification:**

Purchase six duplexes at the south end of Wendy's Way, which are in the RPZ of the Lake Hood Airstrip, remove the dwellings, and address any cul-de-sac reconfiguration that may be required. FAA prohibits structures in RPZ. As part of the 2006 Lake Hood GA Master Plan, various alternatives were considered to resolve the problem, such as relocating or re-orienting the runway, but removal of the duplexes was deemed the most cost effective solution. At completion of the Master Plan, FAA recommended that the Ted Stevens Anchorage International Airport acquire and remove the properties. FAA will not grant a variance of standards to allow the dwellings to remain, as they are a safety hazard, and recommends removal. If the duplexes are not removed, safety risks and violation of FAA standards will continue.

Totals:

0

0