

**Cold Bay - Runway 14/32 Rehabilitation with Lighting System Replacement**

**FY2013 Request: \$16,000,000**  
**Reference No: 36289**

**AP/AL:** Allocation

**Project Type:** Construction

**Category:** Transportation

**Location:** Cold Bay

**House District:** Bristol Bay/Aleutians (HD 37)

**Impact House District:** Bristol Bay/Aleutians (HD 37)

**Contact:** Steve Hatter

**Estimated Project Dates:** 07/01/2012 - 06/30/2019 **Contact Phone:** (907)269-0730

**Appropriation:** Airport Improvement Program

**Brief Summary and Statement of Need:**

Rehabilitate the main runway, install new edge lighting.

<b>Funding:</b>	<u>FY2013</u>	<u>FY2014</u>	<u>FY2015</u>	<u>FY2016</u>	<u>FY2017</u>	<u>FY2018</u>	<u>Total</u>
Fed Rcpts	\$16,000,000						\$16,000,000
<b>Total:</b>	<b>\$16,000,000</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$16,000,000</b>

<input type="checkbox"/> State Match Required	<input checked="" type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
0% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

**Operating & Maintenance Costs:**

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	0
<b>Totals:</b>	<b>0</b>	<b>0</b>

**Additional Information / Prior Funding History:**

None.

**Project Description/Justification:**

This project is needed due to the general pavement condition at the airport, and the age of the lighting system. The Pavement Condition Index (PCI) shows the pavement being below standards (it is between 55 and 69 on the PCI scale and should be 70 or above), the lighting is old and in need of replacement.

This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.