

Gulkana - Apron and Taxiway Pavement Rehabilitation**FY2015 Request:****\$320,000****Reference No:****51574****AP/AL:** Allocation**Project Type:** Construction**Category:** Transportation**Location:** Gulkana**House District:** Bering Straits/Interior Villages (HD 39)**Impact House District:** Bering Straits/Interior Villages (HD 39)**Contact:** Steven Hatter**Estimated Project Dates:** 07/01/2014 - 06/30/2021**Contact Phone:** (907)269-0730**Appropriation:** Airport Improvement Program**Brief Summary and Statement of Need:**

Rehabilitate the pavement on the apron and taxiway.

Funding:	<u>FY2015</u>	<u>FY2016</u>	<u>FY2017</u>	<u>FY2018</u>	<u>FY2019</u>	<u>FY2020</u>	<u>Total</u>
Fed Rcpts	\$320,000						\$320,000
Total:	\$320,000	\$0	\$0	\$0	\$0	\$0	\$320,000

<input checked="" type="checkbox"/> State Match Required	<input type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input checked="" type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
3% = Minimum State Match % Required	<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill		

Operating & Maintenance Costs:

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	
Totals:	0	0

Prior Funding History / Additional Information:

Sec1 Ch17 SLA2012 P138 L33 SB160 \$700,000

Sec1 Ch5 SLA2011 P104 L19 SB46 \$1,730,000

Project Description/Justification:

Reconstruction is recommended by the Airport Pavement Management Report. These surfaces were last paved in 1980. There is a high incidence of block cracking and high severity depression. Normal maintenance and crack sealing is not adequate to address these deficiencies.