\$1,850,000	inder ground	1 Otorage Tai	iik opgiaut	-5 - IVIL	Reference N		616 5 7
AP/AL: Appropriation				Project Type: Renewal and Replacement			
Category: Publi	c Protection			-			
Location: Statewide				House District: Statewide (HD 1-40)			
Impact House District: Statewide (HD 1-40)				Contact: April Wilkerson			
Estimated Proj	ect Dates: 0	6/30/2017 - 0	6/30/2021	Contact	Phone: (907)46	55-3460	
Brief Summary	and Statem	ent of Need:					
The Department	of Correction	ns has tradition	nally used	undergrou	nd storage tank	ks (UST) for h	eating
fuel and generate	or fuel storag	ge. The use of	f one tank fo	or both fue	el sources was t	the most ecor	nomical
way to operate a	•	•				•	_
requirements and	•	its combined	emergency	generato	r and heating fu	el storage wit	thout
monitoring modif		F)/0040	E) (00.40	E) (0000	E) (0004	F)/0000	T ()
Funding:	FY2017	FY2018	FY2019	FY2020	FY2021	FY2022	Total
1213 AHCC Rcpts							\$0
Total:	\$0	\$0	\$0	\$0	\$0	\$0	\$0
☐ State Match Required				- new	☐ Phased - unde	rway 🛚 On-G	oing
0% = Minimum State Match % Required ☐ Amend				nent	☐ Mental Health	Bill	
Operating & Ma	intenance C	costs:			Amou	unt S	taff
Project Devel				pment:		0	
Ongoing Op				•		0	0

EV2018 Doguest

Prior Funding History / Additional Information:

Pospprop for Underground Storage Tank Ungrades - NTE

The unexpended and unobligated balance, not to exceed \$1,850,000, of the appropriation made in sec. 1, ch. 18, SLA 2014, page 50, lines 25 – 27 (Department of Education and Early Development, State Library, Archives and Museum Facility Construction Funding - \$37,500,000) is reappropriated to the Department of Corrections for underground storage tank upgrades.

One-Time Startup:

Totals:

Project Description/Justification:

Most Department of Corrections (DOC) facilities with UST require separation of fuel sources or additional monitoring devices to meet the new compliance requirements. In order to stay compliant with UST 2018 changes to the DEC regulations, any UST fuel oil systems that are tied into generators must meet the new monitoring requirements.

There are issues at five different facilities: Combined Hiland Mountain Correctional, Palmer Correctional, Yukon Kuskokwim Corrections, Spring Creek Correctional, and Anchorage West Correctional. The consequences of not making the modifications are significant. The DEC would tag the fuel tanks out of service and it would be illegal to continue to fill the tanks.